

**Omega Engineering Inc.**  
**TX69 / TXDIN101**  
**Software Loading Instructions**

CONCAL and drivers should be first installed.

**CONCAL installation for Windows 98, XP and Vista**

1. Please insert the CD
2. Please follow the installation wizard instructions
3. Allow installation although the system might not recognize
4. When relevant, please mark "Create a desktop icon"
5. At the end of the installation press "Finish"

**Oxusb Drivers Installation**

1. Please close all the open windows
2. Plug the CON-COM cable to one of the USB ports
3. "Find New Hardware Wizard" window will appear
4. Please mark the "Install from a list or specific location" and unmark "Include this location in the search"
5. Press Next
6. In the next window select "Search removable media"
7. If a warning window will pop up –press "Continue anyway"
8. At the end of the installation press "finish"

**Note:** Usually, the software automatically searches for the USB port. Some times the PC fails to recognize other ports than the one used for the installation.

**Note:** The time it takes for the unit to communicate with the PC varies from 5 to 50 seconds, as a function of the previous setting.