HIGH-ACCURACY DIGITAL **BAROMETER KIT** WITH NIST-TRACEABLE CERTIFICATION

DISCONTINUED

DP1740-KIT





- ✓ Very High Accuracy: ±0.02% Full Scale
- ✓ Measures Absolute or **Sea Level Barometric** Pressure
- Altitude Mode with Local **Height and Temperature** Corrections
- Stability Better Than 100 ppm per Year
- ✓ Standard RS232 Communications

OMEGA's DPI740 is a highaccuracy, handheld barometer suitable for the most demanding field or laboratory applications. It can measure absolute barometric pressure or barometric pressure corrected to sea level. Pressure can be displayed in 1 of 24 different engineering units. In addition, the DPI740 can display altitude in feet or meters.

SPECIFICATIONS

Measuring Range:

23 to 34 in Hg absolute

Accuracy: ±0.02% full scale @ -10 to 50°C (14 to 122°F) Operating Temp: -10 to 50°C

(14 to 122°F)

Storage Temp: -40 to 71°C

(-40 to 160°F)

Safe Overpressure: 0 to 118 inHg will not cause calibration change

Resolution: 0.0003 inHq

Display Update: 2 readings per second

Kit comes complete with rugged transit case, soft carrying case, RS232 cable, and 3 "AA" batteries.





DPI740-KIT. shown smaller than actual size.

Operating Modes: Local pressure, sea level pressure from user-set height. altitude from user-set datum

Units of Measure:

24 selectable scales for pressure, feet or meters for altitude

Process Features: Maximum/minimum, reading store, tare and programmable filter available in all modes

Pressure Media: Non-corrosive

gases only

Pressure Fitting: Hose fitting for 4 mm ID, 6 mm OD (0.157 x 0.236") flexible tubing

Sealing Standard: NEMA 12 (IP54) Power: 3 "AA" batteries (included) provides 20 hours of continuous operation

Dimensions: 190 H x 89 W x 36 mm D

(7.5 x 3.5 x 1.4")

Weight: 0.5 kg (1.1 lb)

To Order	
MODEL NO.	DESCRIPTION
DPI740-KIT	Handheld barometer kit

ACCESSORIES

MODEL NO.	DESCRIPTION
DPI740-BATT	1 Ni-Cad battery (optional, 3 required)
DPI740-CHARGER	115/220 Vac battery charger (optional)

Comes complete with rugged transit case, soft carrying case, RS232 cable, 3 "AA" batteries, NIST calibration certificate and operator's manual.

Ordering Example: DPI740-KIT, handheld barometer kit, 3 of DPI740-BATT, adds rechargeable batteries and DPI740-CHARGER, charger to kit.