1/8 DIN Process Panel Meter With Optional USB Communications



DP6000 Series











- Modular USB, RS232, RS485 Serial Communication Options and Relays
- 0 to 20 mA, 4 to 20 mA, 0 to 5V, 1 to 5V, and ±10V Inputs
- ✓ NEMA 4X (IP65) Front
- Universal 85 to 265 Vac or 12/24 Vdc Input Power
- ✓ Large Dual-Line 6-Character Display, 15 and 12 mm (0.60 and 0.46")
- Sunlight Readable Display Models
- ✓ Isolated 24 Vdc @ 200 mA Transmitter Power Supply Standard
- Programmable Displays and Function Keys
- ✓ 32-Point, Square Root, or Exponential Linearization
- MODBUS® RTU Communication Protocol Standard
- Free Software for Operation, Monitoring and Programming

The DP6000 Series meter boasts specifications and functionality that clearly make it one of the most advanced process meters available. Its dual-line 6-digit display (999,999), advanced signal input conditioning functions, function keys, MODBUS RTU serial communications, and optional expansion modules are only a few of the features found on the DP6000. Sunlight readable display models have an extraordinarily bright LED display. They are perfect for applications where the meter is in direct sunlight or in applications where visibility may be impaired by smoke, fog, dust, or distance. The upper display can be programmed to indicate PV,



maximum (peak), minimum (valley), alternating maximum/ minimum, one of eight alarm set points, or MODBUS input. The lower display can also be configured to display engineering units, set points, user defined legends, or simply turned off. The user friendly dual-line display makes the DP6000 easy to set up and program. No jumpers to set for input selection. All setup and programming are done via the front panel. Three levels of password protection help maintain the reliability of the programming. The Copy feature is used to copy (or clone) all the settings from one DP6000 to other meters in about 20 seconds! The Copy function is a standard feature on all meters. It does not require a communications adaptor, only an optional cable assembly.

General Specifications

Display: Both displays are 6 digits (-99999 to 999999), red LEDs with leading zero blanking

Upper Display: 15 mm (0.60") high Lower Display: 12 mm (0.46") high Display Intensity: 8 intensity levels Display Update Rate: 5/second (200 ms)

Overrange: Display flashes 999999 Underrange: Display flashes -99999 **Display Assignment:** The upper and lower displays may be assigned to PV1, PV2, PCT (percent), max/min, alternate max and min, set points, units (lower display only), or MODBUS input

Front Panel: NEMA 4X (IP65)
Programming Methods: 4 front
panel buttons, digital inputs, PC and
software, MODBUS registers, or
cloning using copy function

Noise Filter: Programmable from 2 to 199 (0 will disable filter)

Filter Bypass: Programmable from 0.1 to 99.9% of calibrated span

Recalibration: Calibrated at the factory. Recalibration is recommended at least every 12 months

Max/Min Display: Max (peak)/ min (valley) readings reached by the process are stored until reset by the user or until power to the meter is cycled

Password: 3 programmable passwords restrict modification of programmed settings; Pass 1: Allows use of function keys and digital inputs; Pass 2: Allows use of function keys, digital inputs and editing set/reset points; Pass 3: Restricts all programming, function keys, and digital inputs

Non-Volatile Memory: All programmed settings are stored in non-volatile memory for a minimum of ten years if power is lost

Power Options: 85 to 265 Vac 50/60 Hz, 90 to 265 Vdc, 20 W max, or jumper selectable 12/24 Vdc ±10%, 15 W max

Fuse (External, Required): UL recognized, 5 A max, slow blow; up to 6 meters may share one 5 A fuse

Isolated Transmitter Power Supply: 24 Vdc ±5% @ 200 mA max (standard), (12/24 Vdc powered models rated @ 100 mA max); 5 or 10 Vdc @ 50 mA max, selectable with internal jumper J4

Normal Mode Rejection: Greater than 60 dB at 50/60 Hz

Isolation: 4 kV input/output-to-power line; 500 V input-to-output or output-to-P+ supply

Overvoltage Category: Installation overvoltage category II; local level with smaller transient overvoltages than installation overvoltage category III

Operating Temperature Range: -40 to 65°C (-40 to 149°F)

Storage Temperature Range: -40 to 85°C (-40 to 185°F)

Relative Humidity: 0 to 90% non-condensing

Connections: Removable screw terminal blocks accept 12 to 22 AWG wire. RJ45 for external relavs. digital I/O, and serial communication adaptors

Enclosure: 1/8 DIN, high impact plastic, UL 94V-0, color: black Mounting: 1/8 DIN panel cutout required: 92 x 45 mm (3.622 x 1.772"); two panel mounting bracket assemblies are provided

Tightening Torque: Screw terminal connectors: 5 lb-in (0.56 Nm)

Overall Dimensions: 119 W x 62 H x 143 mm D (4.68 x 2.45 x 5.64")

Weight: 269 g (9.5 oz) **Process Input**

Input: Field selectable: 0 to 20 mA, 4 to 20 mA, ±10 Vdc (0 to 5, 1 to 5, 0 to 10V), MODBUS PV (slave)

Accuracy: ±0.03% of calibrated span ±1 count, square root and programmable exponent accuracy range: 10 to 100% of calibrated span

Temperature Drift: 0.005% of calibrated span/°C max from 0 to 65°C ambient, 0.01% of calibrated span/°C max from -40 to 0°C ambient

Signal Input Conditioning Function: Linear, square root, programmable exponent, or round horizontal tank volume calculation

Multi-Point Linearization: 2 to 32 points for PV or PV1;

2 to 8 points for PV2 (dual-scale level feature)

Programmable Exponent: 1.0001 to 2.9999

Low-Flow Cutoff: 0 to 999999 (0 disables cutoff function)

Decimal Point: Up to 5 decimal places or none: d.ddddd, dd.dddd, ddd.ddd, dddd.dd, ddddddd, or dddddd

Calibration Range:

4 to 20 mA: Minimum span; input 1 and Input 2: 0.15 mA ±10 V: Minimum span; input 1 and 2: 0.10 V

An Error message will appear if input 1 and input 2 signals are too close together

Input Impedance:

Voltage Ranges: Greater than

Current Ranges: 50 to 100 Ω (depending on resettable fuse

impedance)

Input Overload: Current input protected by resettable fuse, 30 Vdc max; fuse resets automatically after fault is removed

Relavs

Rating: 2 or 4 SPDT (Form C) internal and/or 4 SPST (Form A) external; rated 3 A @ 30 Vdc and 125/250 Vac resistive load; 1/14 HP (≈ 50 W) @ 125/250 Vac for inductive loads such as contactors, solenoids, etc.

Noise Suppression:

Recommended for each relay contact switching inductive loads

Deadband: 0 to 100% of span, user

programmable

High or Low Alarm: User may program any alarm for high or low trip point; unused alarm LEDs and relays may be disabled (turned off)

Relay Operation: Automatic (nonlatching), latching (requires manual acknowledge), sampling (based on time), pump alternation control (2 to 8 relays), off (disable unused relays and enable interlock feature, manual on/off control mode)

Time Delay: 0 to 999.9 seconds, on and off relay time delays; programmable and independent for each relav

Fail-Safe Operation: Programmable and independent for each relay

Note: Relay coil is energized in non-alarm condition. In case of power failure, relay will go to alarm state.

Auto Initialization: When power is applied to the meter, relays will reflect the state of the input to the meter

Serial Communications

Protocol: MODBUS RTU

Meter Address/Slave ID: 1 - 247

Baud Rate: 300 to 19,200 bps

Transmit Time Delay: Programmable

between 0 and 199 ms

Data: 8 bit (1 start bit, 1 or 2 stop bits) Parity: Even, odd, or none with 1 or 2

stop bits

Byte-to-Byte Timeout: 0.01 to 2.54 seconds **Turn Around Delay:** Less than 2 ms (fixed)

Isolated 4 to 20 mA Transmitter Output

Output Source: Process variable (PV), max, min, set points 1 through 8, manual control setting, or

MODBUS input

Scaling Range: 1.000 to 23.000 mA

for any display range

Factory Calibration: 4.000 to 20.000 = 4 to 20 mA output

Analog Output Programming: 23.000 mA maximum for all parameters: overrange, underrange,

max, min, and break

Accuracy: ± 0.1% of span ± 0.004 mA

Temperature Drift: 0.4 µA/°C maximum from 0 to 65°C ambient, 0.8 µA/°C maximum from -40 to 0°C ambient

Note: Analog output drift is separate from

input drift.

Isolated Transmitter Power Supply: Terminals I+ & R: 24 Vdc ± 5% @ 40 mA maximum, may be used to power the 4 to 20 mA output or other devices

External Loop Power Supply: 35 Vdc maximum

Output Loop Resistance: 24 Vdc Power Supply: 10 Ω minimum, 700 Ω maximum 35 Vdc (External) Power Supply: 100 Ω minimum, 1200 Ω maximum

Digital I/O Expansion Module

Channels: 4 digital inputs and 4 digital outputs per module

System: Up to 2 modules for a total of

8 inputs and 8 outputs **Digital Input Logic:** High: 3 to 5 Vdc Low: 0 to 1.25 Vdc

Digital Output Logic: High: 3.1 to 3.3 Vdc Low: 0 to 0.4 Vdc

Source Current: 10 mA maximum Sink Current: 1.5 mA minimum +5 V Terminal: To be used as pull-up

for digital inputs only

4-Relay Expansion Module

Relays: 4 Form A (SPST) rated 3 A @ 30 Vdc and 125/250 Vac resistive load: 1/14 HP (≈ 50 W) @ 125/250 Vac for inductive loads

Meter Copy

The Copy feature is used to copy (or clone) all the settings from one DP6000 to other DP6000 meters in about 20 seconds! The Copy function is a standard feature on all meters. It does not require a communications adapter, only an optional cable assembly, model number DPA1200. See the ordering information for complete details



NEMA 4X Field Enclosures

Thermoplastic NEMA 4X enclosures are constructed for either indoor or outdoor use.



DP6000 with DPA2812 NEMA 4X field enclosure, shown smaller than actual size.

To Order Visit omega.com/dp6000 for Pricing and Details

Standard 85 to 265 Vac ModelsDP6000-6R0Process panel meterDP6000-6R2Process panel meter with 2 relaysDP6000-6R3Process panel meter with 4 to 20 mA outputDP6000-6R4Process panel meter with 4 relaysDP6000-6R5Process panel meter with 2 relays and 4 to 20 mA output

Process panel meter with 4 relays and 4 to 20 mA output

Standard 12/24 Vdc Low Voltage Models

Description

Model No.

DP6000-6R7

DP6000-7R0	Process panel meter
DP6000-7R2	Process panel meter with 2 relays
DP6000-7R3	Process panel meter with 4 to 20 mA output

Sunlight Readable Models, 85 to 265 Vac

DD6000 6H0 Process panel motor

DF0000-0110	Frocess parier meter
DP6000-6H2	Process panel meter with 2 relays
DP6000-6H3	Process panel meter with 4 to 20 mA output

Sunlight Readable Models, 12/24 Vdc Low Voltage

DP6000-7H0	Process panel meter
DP6000-7H2	Process panel meter with 2 relays
DP6000-7H3	Process panel meter with 4 to 20 mA output

Accessories

Accessories	Process paner meter with 4 to 20 mA output
Model No.	Description
DPA1004	4-relay expansion module - field installable
DPA1044	4 digital inputs and 4 digital outputs module - field installable
DPA1232	RS232 serial adaptor - field installable
DPA1485	RS485 serial adaptor - field installable
DPA8008	USB serial adaptor - field installable
DPA7485-I	RS232 to RS422/485 isolated converter - field installable
DPA7485-N	RS232 to RS422/485 non-isolated converter - field installable
DPA8232-N	USB to RS232 non-isolated converter - field installable
DPA8485-I	USB to RS422/485 isolated converter - field installable
DPA8485-N	USB to RS422/485 isolated converter - field installable
DPA1002	DIN rail mounting kit for 2 expansion modules
DPA1200	Meter copy cable
DPA2811	Plastic NEMA 4X enclosure for one DP6070 temperature meter
DPA2812	Plastic NEMA 4X enclosure for two DP6070 temperature meters
0	ation because and an authorization of European CNICCOR COFF and the same described and in the last annual section (4 a core

Comes complete with 2 side mounting brackets and operator's manual. Free **CN6000-SOFT** software download available at **omega.com/dp6000 Ordering Example: DP6000-6R2**, process panel meter with 2 relays, and **DPA8008**, USB serial adaptor. **OCW-2**, OMEGACARESM extends standard 3-year warranty to a total of 5 years.